



NT4008 Industrial Ethernet Managed Switch Series

Firmware Release | August 2021

LP1179 | Revision A

Through Version 1.0.7

COPYRIGHT

©2021 Red Lion Controls, Inc. All rights reserved. Red Lion and the Red Lion logo are registered trademarks of Red Lion Controls, Inc. All other company and product names are trademarks of their respective owners.

Red Lion Controls, Inc.
20 Willow Springs Circle
York, PA 17406

CONTACT INFORMATION:

AMERICAS

Inside US: +1 (877) 432-9908

Outside US: +1 (717) 767-6511

Hours: 8 am-6 pm Eastern Standard Time
(UTC/GMT -5 hours)

ASIA-PACIFIC

Shanghai, P.R. China: +86 21-6113-3688 x767

Hours: 9 am-6 pm China Standard Time
(UTC/GMT +8 hours)

EUROPE

Netherlands: +31 33-4723-225

France: +33 (0) 1 84 88 75 25

Germany: +49 (0) 1 89 5795-9421

UK: +44 (0) 20 3868 0909

Hours: 9 am-5 pm Central European Time
(UTC/GMT +1 hour)

Website: www.redlion.net

Support: support.redlion.net

Table of Contents

NT4008 Industrial Ethernet Managed Switch Release Notes 1
 Document Change History.....1
NT4008 System Firmware..... 3
 Firmware Release Version 1.0.5 to 1.0.7 Delta.....3

NT4008 Industrial Ethernet Managed Switch Release Notes

Document Change History

VERSION	DATE	DESCRIPTION
1.0.7	July 2021	Release 1.0.7 System Firmware

NT4008 System Firmware

Firmware Release Version 1.0.5 to 1.0.7 Delta

- Added Web support for MRP configuration and enhanced CLI MRP configuration.
- Corrected issue where VLANs that were added to IGMP or MLD snooping were not properly reported when *show runningcfg* was executed.
- Fixed problem where MRP ports were incorrectly reported after a *shutdown* or *no shutdown* command was executed.
- Corrected problem where MRP *open* and *close* status was not properly reported in the syslog.

