N-Tron® Series
N-View™ 2

Software Release | January 2023
LP1193 | Revision A
Through Version 1.1.11

COPYRIGHT

©2023 Red Lion Controls, Inc. All rights reserved. Red Lion, the Red Lion logo, N-Tron and N-View are trademarks of Red Lion Controls, Inc. All other company and product names are trademarks of their respective owners.

Red Lion Controls, Inc.
35 Willow Springs Circle
York, PA 17406

CONTACT INFORMATION:

AMERICAS

Inside US: +1 (877) 432-9908
Outside US: +1 (717) 767-6511
Hours: 8 am-6 pm Eastern Standard Time
(UTC/GMT -5 hours)

ASIA-PACIFIC

Shanghai, P.R. China: +86 21-6113-3688 x767
Hours: 9 am-6 pm China Standard Time
(UTC/GMT +8 hours)

EUROPE

Netherlands: +31 33-4723-225
France: +33 (0) 1 84 88 75 25
Germany: +49 (0) 1 89 5795-9421
UK: +44 (0) 20 3868 0909
Hours: 9 am-5 pm Central European Time
(UTC/GMT +1 hour)

Website: www.redlion.net
Support: support.redlion.net

Table of Contents

N-View™ 2 Software Release Notes.....1
Document Change History.....1
N-View™ 2 Software.....3
Software Release Version 1.0. to 1.1.11 Delta.....3

N-View™ 2 Software Release Notes

Document Change History

VERSION	DATE	DESCRIPTION
1.1.11	January 2023	Release 1.1.11 Software

N-View™ 2 Software

Software Release Version 1.0. to 1.1.11 Delta

- Added support for NT5000 devices
- Added support for latest Npcap library (1.72)
- Fixed issues when a false error was reported when doing firmware or bootloader upgrades
- Fixed various issues with the job scheduler
- Improved firmware/bootloader upgrade process
- Fixed issue that prevented firmware/uploader upgrades in computers with more than one network interface card