



## Patch/Update Notification

SN/RAM-6000 Series Announcement

Snpat20140422\_reflashing\_tools.zip

April 2014

# Patch/Update Notification

## Change History

Version	Date	Description
1.0	4-22-2013	Initial Release – TKB

## Patch Information

### Description

Units affected: **SN/RAM-6xxx** for all carriers.

Versions affected: **3.12-3.16, 4.00-4.16**

Versions applied: **All**

This patch improves reflashing reliability when attempting to upgrade to newer firmware. Whether the patch has already been applied, or your unit is operating correctly, it is harmless to apply/re-apply this patch.

It is recommended to apply this patch **prior** to reflashing to a newer version of firmware. A reboot is **not** required for updates to take effect after applying this patch.

This does not apply to Advanced Reflash methods through the pushbutton operation.

This does not apply to RAM9K units.

### Symptoms

- A small percentage of units may not complete reflashing to a newer version of firmware when running SerialIP, DNP3, or Modbus functions.



Sixnet, Inc, A Red Lion Controls Business  
331 Ushers Road, Ballston Lake, NY 12019

**CONNECT. MONITOR. CONTROL.**  
T +1 518 877 5173