



POTENTIALLY HAZARDOUS INSTALLATIONS

ACTION REQUIRED

MODELS AFFECTED: G306A000

RANGE AFFECTED: DATE CODE OF MANUFACTURE – 12103 THROUGH 40105

HAZARD

Units were built without the components necessary to secure the LED power board connectors, with sufficient retention, to meet Hazardous Locations use approval. There is a risk of fire if the user installs affected units in Hazardous Locations.

IDENTIFICATION


Rear Cover - Units have a white label (.375" x 1.25") on rear cover marked with the model identification and date code. Date codes from 12103 through 40105 are affected.

MODELS AFFECTED

G306A000

RANGE AFFECTED

Date Code of Manufacture – 12103 through 40105



-- CONT. --

YOUR ACTION REQUIRED

DISTRIBUTORS

Distributors should forward this notice to all customers who have purchased these models during or after the month of March 2010. Further, any stock that you possess should be inspected to determine whether or not it falls within the date code range shown above.

CUSTOMERS & USERS

Users should not use affected units in potentially hazardous (flammable) environments. Units that are currently installed in hazardous locations should be returned to Red Lion Controls for rework.

QUESTIONS

Contact: Red Lion Controls

Phone: +1 (717) 767-6511

Fax: +1 (717) 764-0839

EMAIL: techsupport@redlion.net

<http://www.redlion.net/>

<http://www.redlion.net/CorporateInfo/ContactInformation.html>