

July 1, 2019

Red Lion Controls, Inc.  
20 Willow Springs Circle  
York, PA 17406 USA

**Ref: The “Conflict Minerals Law” included as “Section 1502 of the Dodd-Frank Wall Street Reform and Customer Protection Act” of the United States of America, requests to identify products which contain “Conflict Minerals”.**

Red Lion Controls does not purchase tin, tungsten, tantalum or gold, which is necessary for most Red Lion Controls products, directly from smelters or mines. All Red Lion Controls electronic products contain gold, tin, tungsten and many contain tantalum. This letter is to advise that based on information from our suppliers of component parts and materials, Red Lion Controls has no reason to believe the minerals, tin, tungsten, tantalum and gold, may have originated in the Democratic Republic of the Congo (DRC) or an adjoining country.

The Red Lion Controls address shown above is our world headquarters and all manufacturing of the products built by us is done at the York facility and all are Country of Origin (COO) – USA.

Best regards,

Kevin Good

Signature of person authorized to sign on behalf of company.

**Signature**



**Name Printed**

**Kevin Good**

**Title Printed**

**Vice President of Global Operations**

**7/1/2019**