

# Product Discontinuation Announcement



**July 31, 2017**

## Product Affected by this Announcement

**Libra Counter and Timers, CUB3 Counters, T48/P48 PID Controllers, T16/P16 PID Controllers, and TLA Temperature Limit Alarms**

Red Lion Controls announces the end of life (EOL) of the following products. Final purchases will be accepted based on product availability. Red Lion will continue to repair products as long as parts remain available.

### *April 5, 2018 Update*

Due to an overwhelming number of large quantity orders for the **P48/T48, P16/T16 and TLA** models, we now have a limited supply of raw materials with which to build the product. Therefore, effective immediately, these products are on a build-to-order status. They will continue to be offered until our supplies are depleted or until the original end date, whichever comes first.

Part Number	Suggested Replacement	Last NCNR Order Entry*	Shipments Cease*
LIBC1000	CUB5 or PAX (see <a href="#">replacement guide</a> )	9/30/2017	12/31/2017
LIBC1010	CUB5 or PAX (see <a href="#">replacement guide</a> )	9/30/2017	12/31/2017
LIBC1E00	CUB5 or PAX (see <a href="#">replacement guide</a> )	9/30/2017	12/31/2017
LIBC1E10	CUB5 or PAX (see <a href="#">replacement guide</a> )	9/30/2017	12/31/2017
LIBC2000	CUB5 or PAX (see <a href="#">replacement guide</a> )	9/30/2017	12/31/2017
LIBC2010	CUB5 or PAX (see <a href="#">replacement guide</a> )	9/30/2017	12/31/2017
LIBC2E00	CUB5 or PAX (see <a href="#">replacement guide</a> )	9/30/2017	12/31/2017
LIBC2E10	CUB5 or PAX (see <a href="#">replacement guide</a> )	9/30/2017	12/31/2017
LIBT1000	CUB5 or PAX (see <a href="#">replacement guide</a> )	9/30/2017	12/31/2017
LIBT1010	CUB5 or PAX (see <a href="#">replacement guide</a> )	9/30/2017	12/31/2017
LIBT1E00	CUB5 or PAX (see <a href="#">replacement guide</a> )	9/30/2017	12/31/2017
LIBT1E10	CUB5 or PAX (see <a href="#">replacement guide</a> )	9/30/2017	12/31/2017
LIBT2000	CUB5 or PAX (see <a href="#">replacement guide</a> )	9/30/2017	12/31/2017
LIBT2010	CUB5 or PAX (see <a href="#">replacement guide</a> )	9/30/2017	12/31/2017
LIBT2E00	CUB5 or PAX (see <a href="#">replacement guide</a> )	9/30/2017	12/31/2017
LIBT2E10	CUB5 or PAX (see <a href="#">replacement guide</a> )	9/30/2017	12/31/2017
CUB30000	CUB7CCS0	9/30/2018	12/31/2018
CUB3B000	CUB7CCS0	9/30/2018	12/31/2018
CUB3BR00	CUB7CCS0	9/30/2018	12/31/2018
CUB3L000	CUB7CCS0	9/30/2018	12/31/2018
CUB3LR00	CUB7CCS0	9/30/2018	12/31/2018
CUB3R000	CUB7CCS0	9/30/2018	12/31/2018
P1610000	PXU10020	9/30/2018	12/31/2018
P1610010	PXU100B0	9/30/2018	12/31/2018
P1611100	PXU11A20	9/30/2018	12/31/2018

\*Dates may be subject to change depending on product sales

<b>Part Number</b>	<b>Suggested Replacement</b>	<b>Last NCNR Order Entry*</b>	<b>Shipments Cease*</b>
P1611110	PXU11AB0	9/30/2018	12/31/2018
P1620000	PXU20020	9/30/2018	12/31/2018
P1621100	PXU21A20	9/30/2018	12/31/2018
P1621110	PXU21AB0	9/30/2018	12/31/2018
P1641100	PXU31A20 or PXU41A20	9/30/2018	12/31/2018
P1641110	PXU31AB0 or PXU41AB20	9/30/2018	12/31/2018
P4800001	PXU30020 or PXU40020	9/30/2018	12/31/2018
P4800011	PXU300B0 or PXU400B0	9/30/2018	12/31/2018
P4810000	PXU10020	9/30/2018	12/31/2018
P4810010	PXU100B0	9/30/2018	12/31/2018
P4810101	PXU31A20 or PXU41A20	9/30/2018	12/31/2018
P4810105	Contact Tech Support	9/30/2018	12/31/2018
P4810107	PXU31AB0 or PXU41AB0	9/30/2018	12/31/2018
P481010A	Contact Tech Support	9/30/2018	12/31/2018
P4810111	PXU31AB0 or PXU41AB0	9/30/2018	12/31/2018
P4810115	Contact Tech Support	9/30/2018	12/31/2018
P4810117	PXU31AB0 or PXU41AB0	9/30/2018	12/31/2018
P481011A	Contact Tech Support	9/30/2018	12/31/2018
P4811100	PXU11A20	9/30/2018	12/31/2018
P4811102	PXU11A20	9/30/2018	12/31/2018
P4811110	PXU11AB0	9/30/2018	12/31/2018
P4811112	PXU11B20	9/30/2018	12/31/2018
T1610000	PXU10020	9/30/2018	12/31/2018
T1610010	PXU100B0	9/30/2018	12/31/2018
T1611000	PXU10020	9/30/2018	12/31/2018
T1611010	PXU100B0	9/30/2018	12/31/2018
T1611100	PXU11A20	9/30/2018	12/31/2018
T1611110	PXU11AB0	9/30/2018	12/31/2018
T1620000	PXU20020	9/30/2018	12/31/2018
T1620010	PXU200B0	9/30/2018	12/31/2018
T1621000	PXU21A20	9/30/2018	12/31/2018
T1621010	PXU21AB0	9/30/2018	12/31/2018
T1621100	PXU21A20	9/30/2018	12/31/2018
T1621110	PXU21AB0	9/30/2018	12/31/2018
T1641100	PXU21A20 or PXU41A20	9/30/2018	12/31/2018
T1641110	PXU21B20 or PXU41B20	9/30/2018	12/31/2018
T4810000	PXU10020	9/30/2018	12/31/2018
T4810002	PXU11A20	9/30/2018	12/31/2018
T4810010	PXU100B0	9/30/2018	12/31/2018
T4810012	PXU11AB0	9/30/2018	12/31/2018
T4810101	PXU31A20 or PXU41A20	9/30/2018	12/31/2018
T4810105	Contact Tech Support	9/30/2018	12/31/2018
T4810106	Contact Tech Support	9/30/2018	12/31/2018
T4810107	PXU31A20 or PXU41A20	9/30/2018	12/31/2018
T4810108	Contact Tech Support	9/30/2018	12/31/2018
T4810109	Contact Tech Support	9/30/2018	12/31/2018
T481010A	Contact Tech Support	9/30/2018	12/31/2018
T4810111	PXU31AB0 or PXU41AB0	9/30/2018	12/31/2018
T4810115	Contact Tech Support	9/30/2018	12/31/2018

<b>Part Number</b>	<b>Suggested Replacement</b>	<b>Last NCNR Order Entry*</b>	<b>Shipments Cease*</b>
T4810116	Contact Tech Support	9/30/2018	12/31/2018
T4810117	PXU31AB0 or PXU41AB0	9/30/2018	12/31/2018
T4810118	Contact Tech Support	9/30/2018	12/31/2018
T4810119	Contact Tech Support	9/30/2018	12/31/2018
T481011A	Contact Tech Support	9/30/2018	12/31/2018
T4811000	PXU11A20	9/30/2018	12/31/2018
T4811010	PXU11AB0	9/30/2018	12/31/2018
T4811012	PXU11AB0	9/30/2018	12/31/2018
T4811100	PXU11A20	9/30/2018	12/31/2018
T4811102	PXU11A20	9/30/2018	12/31/2018
T4811103	Contact Tech Support	9/30/2018	12/31/2018
T4811104	Contact Tech Support	9/30/2018	12/31/2018
T4811110	PXU11AB0	9/30/2018	12/31/2018
T4811112	PXU11AB0	9/30/2018	12/31/2018
T4811113	Contact Tech Support	9/30/2018	12/31/2018
T4811114	Contact Tech Support	9/30/2018	12/31/2018
T4820000	PXU20020	9/30/2018	12/31/2018
T4820010	PXU200B0	9/30/2018	12/31/2018
T4820200	Contact Tech Support	9/30/2018	12/31/2018
T4820201	Contact Tech Support	9/30/2018	12/31/2018
T4820205	Contact Tech Support	9/30/2018	12/31/2018
T4820206	Contact Tech Support	9/30/2018	12/31/2018
T4820208	Contact Tech Support	9/30/2018	12/31/2018
T4820209	Contact Tech Support	9/30/2018	12/31/2018
T4820210	Contact Tech Support	9/30/2018	12/31/2018
T4820211	Contact Tech Support	9/30/2018	12/31/2018
T4820215	Contact Tech Support	9/30/2018	12/31/2018
T4820216	Contact Tech Support	9/30/2018	12/31/2018
T4820218	Contact Tech Support	9/30/2018	12/31/2018
T4820219	Contact Tech Support	9/30/2018	12/31/2018
T4821000	PXU21A20	9/30/2018	12/31/2018
T4821010	PXU21AB0	9/30/2018	12/31/2018
T4821100	PXU21A20	9/30/2018	12/31/2018
T4821102	PXU21A20	9/30/2018	12/31/2018
T4821110	PXU21AB0	9/30/2018	12/31/2018
T4821112	PXU21AB0	9/30/2018	12/31/2018
T4832200	Contact Tech Support	9/30/2018	12/31/2018
T4832210	Contact Tech Support	9/30/2018	12/31/2018
TLA11100	Contact Tech Support	9/30/2018	12/31/2018
TLA11110	Contact Tech Support	9/30/2018	12/31/2018
TLA21000	Contact Tech Support	9/30/2018	12/31/2018
TLA21010	Contact Tech Support	9/30/2018	12/31/2018

Why is this transition taking place?

The CUB7 counters were designed with new features that meet or exceed those available on the CUB1.

W  
Ma  
des  
rep  
pric  
Ple

## Product End of Life Notice

Rev 3/2017

CUB1 to CUB7 Counter Comparison



### Introduction

The CUB1 was introduced in 1982 as one of Red Lion's first counters – an innovative alternative to existing electro mechanical counters. With over 30 years of sales, many customers continue to use the product today. In 2009, we launched the CUB7 counter as the new and improved replacement. It features all plastic construction, a built-in battery, DIP switch programming, and a better price. Despite its continued value, given the availability of critical parts and the CUB7 counters' compelling advantages, it is necessary to discontinue the CUB1 counter.

This document describes the alternatives available and provides information on how their features compare with one another.

### Timing

Red Lion Controls intends to honor the standard warranty obligation for this product when ordered and delivered in accordance with the following transition schedule:



#### March 2017

- Announcement to customers
- Red Lion begins accepting non-cancellable, non-returnable last time buy orders
- Orders may be scheduled for delivery between March 2017 and December 31, 2017

#### September 30, 2017

- General availability of CUB1 counters ceases
- Acceptance of last time buy orders concludes

Customers should take this opportunity to investigate transitioning to our suggested replacements. To help with this, we have created a set of documents which explain the situation and provide additional detail on the differences between the discontinued product and the suggested replacement. These documents are available at:

[www.redlion.net/eol](http://www.redlion.net/eol)

Visit [www.redlion.net](http://www.redlion.net) to learn more about Red Lion's product portfolio. If you have questions or need more information, please contact your local sales representative or Red Lion Technical Support at +1 (877) 432-9908 or +1 (717) 767-6511.